

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
1	BRS	L1	2708	vehicle same (switching or cutting) same off same (drive or power)	USPAT; EPO; JPO; DERWENT	2004/06/16 08:12			0
2	BRS	L2	13	vehicle same (switching or cutting) same off same (drive or power) same (coasting or coast)	USPAT; EPO; JPO; DERWENT	2004/06/16 08:13			0
3	BRS	L3	2	vehicle same (switching or cutting) same off same (drive or power) same (coasting or coast) same signal	USPAT; EPO; JPO; DERWENT	2004/06/16 08:13			0
4	BRS	L4	1	vehicle same (switching or cutting) same off same (drive or power) same (coasting or coast) same auxiliary	USPAT; EPO; JPO; DERWENT	2004/06/16 08:14			0
5	BRS	L5	0	vehicle same "switching-off" same (drive or power) same (coasting or coast) same auxiliary	USPAT; EPO; JPO; DERWENT	2004/06/16 08:15			0
6	BRS	L6	2	vehicle same "control unit" same (drive or power) same (coasting or coast) same auxiliary	USPAT; EPO; JPO; DERWENT	2004/06/16 08:16			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
7	BRS	L7	65	477/33	USPAT; EPO; JPO; DERWEN T	2004/06/16 08:17			0
8	BRS	L8	243	477/108	USPAT; EPO; JPO; DERWEN T	2004/06/16 08:17			0
9	BRS	L9	604	477/121	USPAT; EPO; JPO; DERWEN T	2004/06/16 08:17			0